Page 1 of 1

Suzanne Steab - February 2010 Inspection Report

From:

Karl Houskeeper

To:

Iroberts@archcoal.com; mdavis@archcoal.com

Date:

3/23/2010 8:55 AM

Subject:

February 2010 Inspection Report

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments:

SUFCO February 2010.pdf

Attached is the February 2010 inspection report for SUFCO.

Thanks,

Karl



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER

Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:

OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0410002
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, February 03, 2010
Start Date/Time:	2/3/2010 5:45:00 AM
End Date/Time:	2/3/2010 2:30:00 PM
Last Inspection:	Tuesday, January 26, 2010

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Partly Cloudy, Temp. 9 Deg. F. InspectionID Report Number: 2260

Accepted by: jhelfric

3/22/2010

Permitee: CANYON FUEL COMPANY LLC
Operator: CANYON FUEL COMPANY LLC

Site: SUFCO MINE

Address: 397 S 800 W, SALINA UT 84654

County: SEVIER

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership	Types of Operations
V Federal	✓ Underground

25,292.43 Total Permitted	✓ Federal	✓ Underground
48.43 Total Disturbed	✓ State	☐ Surface
Phase I	☐ County	☐ Loadout
Phase II	☐ Fee	Processing
Phase III	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

LeLand Roberts SUFCO was in attendance during the inspection.

Inanastaria Cianata		1			100000000000000000000000000000000000000
inspector's Signature:	Harl	B. Nou	keese	Date	Wednesday, February 03, 2010

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Inspection Continuation Sheet

Inspection Type: PARTIAL

Inspection Date: Wednesday, February 03, 2010

Page 2 of 3

REVIEW OF PERMIT. PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		V	
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	П	П	П	П

Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Wednesday, February 03, 2010

Page 3 of 3

2. Signs and Markers

The mine identification signs located at the point of public access at the refuse pile and mine site contained the required information.

4.a Hydrologic Balance: Diversions

All diversions are still snow covered.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile appeared stable. No visible hazards observed.

8. Noncoal Waste

Noncoal waste is being stored in the approved storage facility and then loaded into trash bins and hauled off site.